Honeywell

Honeywell Commercial Security
715 Peachtree St.NE
Atlanta, GA 30308
www.security.honeywell.com

July 1, 2021

Dear Valued Customer;

Included in this letter are the latest firmware versions for Honeywell Access Control hardware products. Your product/device will continue to work using older firmware however, Honeywell recommends that organizations install the latest version available to help with enhanced security or to access new functionality.

Firmware Information –Released Firmware Versions
Pro-Watch® 5.0
   • PW7K1IC firmware version 1.29.5.0648 (SP1 or higher required for native mode)
   • PW6K1IC firmware version 2.12.0.0633
   • PW6K1ICE firmware version 1.29.1.0633
   • PW5K1IC firmware version 2.092

Pro-Watch® 4.5
   • PW7K1IC firmware version 1.29.5.0648 (SP3 or higher required for native mode)
   • PW6K1IC firmware version 2.11.4.0609
   • PW6K1ICE firmware version 1.27.2.0607
   • PW5K1IC and PW3K1IC firmware version 2.092

Pro-Watch® 4.4, 4.3.5 and 4.3
   • PW6K1IC firmware version 2.080
   • PW6K1ICE firmware version 1.22.9
   • PW5K1IC and PW3K1IC firmware version 2.092

Current versions of Pro-Watch software are available for download at https://MyWebtech.Honeywell.com
NOTE: Latest supported firmware files are included within Pro-Watch installation.

If you would like any updated software for your test environment or if you have any questions, please let me know. My contact information is listed below.

Thank you for being a Honeywell customer!

Regards,

Ronda Sylvester

Sr. Offering Manager

ronda.sylvester@Honeywell.com