Honeywell

Date: Mar 08, 2022
Region: Global

Please note, the following OmniAssure Touch Readers have been discontinued and declared obsolete and at end of life effective immediately. Where available, replacement SKUS have been noted below. Please refer to your most recent price list or contact your Honeywell sales representative or Honeywell Customer Service for more information.

End of Sales Date: Effective Immediately

End of Life/Support Date: Effective Immediately

Discontinued SKU	Discontinued SKU Description	SKU Replacement	SKU Replacement Description
OmniAssure™ Touch Readers			
OT3300BHONG	OmniAssure Touch MultiTech Mullion 0k	OS20TOSDP	OmniSmart 20, BLK/SLVR Terminal, Standard Profile, OSDP V2
OT3312BHONG	OmniAssure Touch MultiTech Mullion 12k	OS20KTOSDP	OmniSmart 20, BLK/SLVR Terminal, Standard Profile, OSDP V2 W/ Keypad
OT4800BHONG	OmniAssure Touch MultiTech Square 0k	LU4700BHONA	luminAXS Mifare DESFire 0key OSDP reader
OT4816BHONG	OmniAssure Touch MultiTech Square 16k	LU4716BHONA	luminAXS Mifare DESFire 16key OSDP reader
OT3200BHONG	OmniAssure Touch SmartTech Mullion 0k	OS20TOSDP	OmniSmart 20, BLK/SLVR Terminal, Standard Profile, OSDP V2
OT3212BHONG	OmniAssure Touch SmartTech Mullion 12k	OS20KTOSDP	OmniSmart 20, BLK/SLVR Terminal, Standard Profile, OSDP V2 W/ Keypad
OT4700BHONG	OmniAssure Touch SmartTech Square 0k	LU4700BHONA	luminAXS Mifare DESFire 0key OSDP reader
OT4716BHONG	OmniAssure Touch SmartTech Square 16k	LU4716BHONA	luminAXS Mifare DESFire 16key OSDP reader